

Santa Ynez River Water Conservation District, Improvement District No.1

Addendum 2

Dated November 22, 2022

CONTRACT DOCUMENTS FOR

**Zone 3 Concrete Tank – Cleaning and Repair**

Notice is hereby given to prospective bidders that the contract documents for the above project are amended as follows:

**Item No. 1 – TECHNICAL SPECIFICATIONS - Bid Item 2 – Tank Cleaning and Inspection, Page TS.2**

During the initial cleaning of the tank, sediment collected and brought to the surface through the access hatch may be disposed of in a convenient location on site for later removal by the District. As an alternative to removing the bulk of the accumulated sediment through the access hatch, sediment may be disposed of and flushed out through the drain valve (see Photo 12 – Floor Drain) along with adequate water to avoid plugging of the drain piping.

Note to Bidder: Failure to acknowledge this addendum by number and date, on the Bidder's Proposal, Page BR.7, will render the bid non-responsive and may be cause for its rejection.



Photo 12 - Floor Drain